






Formes de plateaux tournants:




CT 460-1	CT 500-1	CT 610-1	CT 710-1	CT 720-1	CT 720-2	CT 810-1	CT 820-2
$r = 230$	$r = 250$	$r = 305$	$r = 355$	$r = 360$	$r = 360$	$r = 405$	$r = 410$
$x = 201$	$x = 220$	$x = 263$	$x = 330$	$x = 310$	$x = 225$	$x = 355$	$x = 325$
$a = 27$	$a = 30$	$a = 42$	$a = 25$	$a = 50$	$a = 135$	$a = 50$	$a = 85$




CT 500-5	CT 720-5	CT 820-5
$r = 250$	$r = 360$	$r = 410$
$x = 130$	$x = 250$	$x = 315$
$r1 = 200$	$r1 = 200$	$r1 = 400$




CT 500-6	CT 720-6	CT 810-6	CT 820-6
$r = 250$	$r = 360$	$r = 405$	$r = 410$
$x = 205$	$x = 283$	$x = 290$	$x = 360$




CT 710-3	CT 810-3
$r = 355$	$r = 405$
$x = 230$	$x = 320$
$a = 125$	$a = 85$



CT 460-4	CT 500-4	CT 610-4	CT 710-4	CT 720-4	CT 810-4	CT820-4
$r = 230$	$r = 250$	$r = 305$	$r = 355$	$r = 360$	$r = 405$	$r = 410$



ST 650-0	ST 750-0	ST 850-0
$r = 325$	$r = 375$	$r = 425$
$a = 60$	$a = 60$	$a = 60$



ST 700-0
$r = 325$
$a = 60$